TECHNICAL DATA SHEET

REVISION: 27/05/2022



FLEX 98A

SMARTFIL® FLEX 98A is a thermoplastic polyurethane that has been additive to obtain a filament that allows printing flexible objects with a certain elasticity, being easier to print than other more common flexible filaments, since it has a higher hardness with respect to these, so it works with a wide range of printers of all kinds, such as direct extrusion or bowden.

For certain applications, such as objects subjected to great stress or vibration, it can be a very useful material, in addition, very good adhesion between layers and a high impact resistance.







<i>' </i>	
Flexible	Impact resistance

	VALUES		UNIT OF MEASUREMENT	STANDARD
PHYSICAL PROPERTIES				
Chemical name Density	Polyurethane		g/cm³	ASTM D792
MECHANICAL PROPERTIES ¹	XY PLAN	ZX PLAN		
Tensile strength	-	-	MPa	ISO 527
Traction module	-	-	MPa	ISO 527
Flexion strength	-	-	MPa	ISO 178
Flexion module	-	-	MPa	ISO 178
Elongation at maximum effort	-	-	%	ISO 527
Charpy Impact Force (without notch)	-	-	kJ/m2	ISO 179
Hardness	98		Shore A	ISO 7619-1

⁽¹⁾ Values obtained on printed specimens, nozzle 0,4 mm, rectilinear infill 100%, layer height 0,2 mm. For more information please contact us by email at info@smartmaterials.com or visit our website

THERMAL PROPE	ERTIES				
Thermal deflec	ction temperature	-		ōС	ASTM E2092
PRINT PROPERTI	IES				
Printing tempe	erature	220-240		ōC	
Bed temperati	ure	0-60		ōC	
Layer fan		60-80		%	
Flow		100		%	
Layer height		≥ 0. 1		mm	
Nozzle recomm	mendations	≥ 0. 2		mm	
Print speed		20-35		mm/s	
SIZE	NET WEIGHT	GROSS WEIGHT	DIAMETER	COLOR	PACKAGING
SILL	ITE! WEIGHT	CHOSS WEIGHT	DII MALLEN	CCLON	1710101011110
M	750g	975g	1.75mm/2.85mm	Several	ZIP Closing Bag

NOTICE: The information provided in the data sheets is intended to be for reference only. It should not be used as design values or quality control. Actual values can differ significantly depending on printing conditions. The final performance of printed components not only depends on the materials, design and printing conditions are also important.